## **Energy Performance Certificate (EPC)**

**Dwellings** 

# **Scotland**

#### FLAT 2/1, 41 ORISSA DRIVE, DUMBARTON, G82 1AB

**Dwelling type:** Date of assessment: Date of certificate:

Top-floor flat 26 June 2018

Total floor area:

71 m<sup>2</sup> 113 kWh/m<sup>2</sup>/year

**Primary Energy Indicator:** 

Reference number: 26 June 2018

Type of assessment: **Approved Organisation:** Main heating and fuel:

2064-1024-9206-1478-5900 RdSAP, existing dwelling

**Elmhurst** 

Boiler and radiators, mains

gas


#### You can use this document to:

· Compare current ratings of properties to see which are more energy efficient and environmentally friendly

### Estimated energy costs for your home for 3 years\*

£1,149

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band B (82). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### (81-91) B 85 85 C (69-80)(55-68) E (39-54 F (1-20) G Not environmentally friendly - higher CO<sub>2</sub> emissions

### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is band B (85). The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE